

## Foreign activities of Dekonta company-reference projects

### Central Europe

#### Hungary

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Site investigation at Mateszalka (Carl Zeiss Vision plant)</b>	URS Germany	Installation of monitoring wells, shallow soil borings, atmogeochemical measurements, pumping tests	2008-2009
<b>Continental - Environmental impact assessment study</b>	Continental Hungary	Elaboration of EIA study for construction of tyre - testing facility in Hungary	2008
<b>Tokod Hungary - Phase I EDDA</b>	URS Germany	Environmental due diligence assessment of Tokod Hungary site	2008
<b>AGJ Hungary - Phase I and Phase II EDDA</b>	POYRY Finland	Environmental audit and investigation of an engineering plant in Hatvan and Jaszbereny	2006

#### Slovakia

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Old environmental burdens in chemical plant Istrochem, Bratislava, Slovakia</b>	Istrochem plant	Site investigation Risk Assessment Clean up design	2008-2009
<b>Remediation of former logistic sites in Pozdišovce and Ružomberok, Slovakia</b>	SLOVNAFT refinery	Site investigation Implementation design Biodegradation treatment of contaminated soil Groundwater remediation	2004-2010
<b>Remediation of 48 former crude oil extraction sites at Gbely oilfield, Slovakia</b>	NAFTA a.s	Sites clean up	2005

## Poland

Project title	Client/Beneficiary	Short description of provided services	Contract Period
Reclamation system instalation on the site of Army Base in Mirosławiec, Poland	RZI Szczecin (Regional Army Administration)	Reclamation system instaling and its first stage operation	2008 - 2009
Reclamation works in the area of leakage on rails in Kędzierzyn Koźle	PKP PLK S.A. Zakład Linii Kolejowych w Gliwicach	Contaminated by ethylbenzene leakage ground and water reclamation, monitoring	2008 - 2011
Reclamation works on the site of JET petrol station in Piła, Poland	ConocoPhillips Poland Sp. z o. o.	The determination of contamination and ground and water environment reclamation	2006 - 2009
Drainage and water purifictaion system installing on the site of Fuel Store in Katowice, Poland	PKN ORLEN S.A.	Drainage and water purifictaion system installing	2007 - 2008
Drainage installing and reclamation works on the site of former Fuel Store in Limanowa –Sowliny	Starostwo Powiatowe in Limanowa	Drainage and water purifictaion system installing, fuel tanks desmantling, free product removal, contaminated water pumping and purification	2007 - 2008
<b>Remediation of oil sludge waste around crude oil extraction wells</b>	Zakład Robót Górniczych w Krośnie	Remediation of 12 former crude oil extraction sites	2003-2006

## Southeastern Europe

### Albania

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Zhares-Oil Sludge Lagoons-Waste Treatability Study</b>	UNDP Regional Centre in Bratislava/ UNDP Tirana office	Site Investigation Laboratory and on site tests on waste treatability Treatability study elaboration	2008
<b>Feasibility study on remediation of contaminated soil at Patos Marinza oil field</b>	UNDP Regional Centre in Bratislava/ UNDP Tirana office	Site Investigation Laboratory and Pilot-scale tests of biodegradation of the soil contaminated with petroleum hydrocarbons Feasibility study on remediation	2006-2007
<b>Evaluation of Patos-Marinza Hot Spot Site in Albania</b>	UNDP Tirana	Feasibility study elaboration	2005 - 2006

### Bosnia and Hercegovina

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Remediation of four SFOR military sites</b>	Defense Construction Canada / Canadian Ministry of Defense	Biodegradation of 5000 t of the soil contaminated with petroleum hydrocarbons, groundwater remediation	2003-2004

### Kosovo

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Consulting services for Environmental Assessment and Remedial Action Plan for Mitrovica Industrial Park</b>	UNDP Regional Centre Bratislava/ UNDP Pristina	Site investigation Risk Assessment Remediation Action Plan	2009

### Macedonia

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Old environmental burdens in chemical plant OHIS, Skopje</b>	Ministry of the Environment of the Czech Republic	Detailed site investigation Hydrogeological monitoring wells installation Risk Assessment elaboration Feasibility Studies elaboration	2007-2009
<b>Feasibility Study for Lojane Mine site</b>	UNDP Regional Centre in Bratislava/UNDP country office Macedonia	Site investigation Mining waste characterization Waste treatability tests Feasibility study elaboration Proposal for a remediation measures Corrective measures and monitoring plan elaboration	2007
<b>Soil cleaning area N25 BFI APOD, Petrovec</b>	NATO HQ Skopje	Biodegradation treatment of petroleum hydrocarbon contaminated soil	2005

### Moldova

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Old environmental burden Iargara - remediation of oil contamination</b>	Ministry of the Environment of the Czech Republic	Site investigation Risk Assessment elaboration Groundwater remediation	2006-2009

### Romania

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Investigation of 19 oil sludge lagoons</b>	PETROM-OMV	Site investigation	2008
<b>Pilot scale bioremediation of soil contaminated with organic compounds at the former pharmaceuticals producing site Terapia in Cluj-Napoca, Romania</b>	WSP Environmental UK/ Terapia, s.a.	Pilot scale remediation of soil contaminated with organic compounds at the former pharmaceuticals producing site	2006
<b>Investigation of oil sludge lagoons at Arpechim refinery area in Pitesti, Romania</b>	Ecovalor SRL/ Petrom S.A	Investigation of 7 lagoon sites Sludge treatability study	2006
<b>Investigation of two oil sludge lagoons in Ploiesti, evaluation of oil sludge treatability, elaboration of Remediation Design</b>	Petrotel-Lukoil	Site investigation Treatability tests Elaboration of preliminary clean up design	2005
<b>Treatment of oily waste from Steaua Romana refinery oil sludge lagoons in Campina</b>	S.C. RAFINARIA STEAUA ROMÂNIA S	Site investigation Quantification of oil sludge volume Treatability tests	2000 - 2003

## Serbia

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Site investigation and rehabilitation of Ada Huja area</b>	Ministry of the Environment of the Czech Republic	Site investigation Risk assessment (dump site, Dunavac bay) Pilot test of Dunavac bay clean up Clean-up design	2008-2010
<b>Introduction of Integrated Waste Management System in selected cities and villages in Vojvodina Province</b>	Ministry of the Environment of the Czech Republic	Quantity and composition of generated waste determination Regional waste management plan elaboration Preliminary design of the Waste Transfer Station Public awareness campaign	2006-2009
<b>Soil and oil sludge treatment in refinery Novi Sad, Serbia</b>	Ministry of Industry and Trade/NIS Oil refinery	Site investigation Pilot tests Feasibility study	2006-2010
<b>Follow up of the environmental hotspots clean-up projects started by UNEP</b>	Ministry of the Environment /NIS refinery, Petrochemija	Groundwater remediation S Site investigation Pilot tests on biodegradation , treatability study	2005-2007
<b>Reduction of human health and environmental risks associated with contaminated sediments at Cukaricki rukavac through identification of sediment clean-up technologies</b>	UNDP Regional Centre in Bratislava	Sampling, chemical and microbiological analysis of the sediments Performance of laboratory scale treatability tests Pre-feasibility study elaboration	2005-2006
<b>Clean up and Revitalization of Veliki Backi Canal in the City of Vrbas</b>	Ministry of the Environment	Site investigation Pilot tests, feasibility study	2004-2006
<b>Remediation of the PetroHemija site in Pancevo, Yugoslavia</b>	Ministry of Industry of the Czech Republic UNEP / UNOPS	Design and installation of a remediation system; remediation of groundwater with massive contamination of dichloroethane	2002-2004
<b>Remediation of former fuel storage in Bogutovac</b>	Ministry of the Environment / Beopetrol	Bioremediation of soil polluted with petroleum hydrocarbons Groundwater remediation	2002-2004

### Turkey

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Pilot evaluation study for the treatment of oil sludge</b>	TUPRAS refinery	Pilot tests on solidification/stabilisation of the oil sludge waste containing heavy metals and petroleum hydrocarbons	2006-2007
<b>Pilot tests on biodegradation treatment</b>	TUPRAS refinery	Pilot tests on biodegradation of the soil contaminated with petroleum hydrocarbons	2009

### Albania, Serbia, Turkey

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Environmental Consultancy Assignments</b>	EBRD, various clients	Environmental due diligence, Environmental and social impact assessment IPPC permitting	continuously

## Post-soviet countries

### Azerbaijan

Project title	Client/Beneficiary	Short description of provided services	Contract Period
Remediation of Buzovna-Mashtaga locality	KAP/ State oil company	Pilot bioremediation tests performed on the sample of 1800 m3 of contaminated soils and sludge, clean up design	2002-2003

### Lithuania

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Sludge Lagoons Clean-up</b>	AB Mazeikiu Nafta	Feasibility study and preliminary remedial design Pilot tests Final clean up design	2009
<b>Investigation of oil sludge lagoons at AB Mazeikiu Nafta refinery</b>	AB Mazeikiu Nafta	Site investigation	2007

### Moldova

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Old environmental burden Iargara - remediation of oil contamination</b>	Ministry of the Environment of the Czech Republic	Site investigation Risk Assessment elaboration Groundwater remediation	2006-2009

### Russia

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Feasibility study and Implementation design of oil sludge lagoons remediation in TNK-BP refinery, Ryazan</b>	TNK-BP Ryazan Refinery	Site investigation, Quantification of oil sludge Treatability tests Feasibility study, clean up design	2005-2006
<b>Remediation and recultivation of highly contaminated areas of Usinsky rajon in Komi republic, Russian federation</b>	LUKOIL	Pilot tests clean up of the unsaturated zone contaminated by petroleum hydrocarbons Detailed clean up design	2002-2004

### Armenia, Estonia, Georgia, Russia, Ukraine

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Environmental Consultancy Assignments</b>	EBRD, various clients	Environmental due diligence, Environmental and social impact assessment IPPC permitting	continuously

## Asia

### Indonesia

Project title	Client/beneficiary	Short description of provided services	Contract Period
<b>Rehabilitation of Tondano lake watershed</b>	Mott McDonald	Field survey of the lake watershed Source identification of the heavy metals, microbiological, PCB and pesticides contamination	2008 - 2009

### Philippines

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Assistance in Guimaras oil spill in Philippines – expert mission in the sphere of bioremediation</b>	European Commission/ Ministry of Internal Affairs	Contamination research Bioremediations laboratory model tests of contaminated soil and water samples	2006

### Vietnam

Project title	Client/Beneficiary	Short description of provided services	Contract Period
<b>Rehabilitation of Thua Thien Hue province affected with AO/dioxin contamination</b>	Ministry of the Environment of the Czech Republic	Field survey (including soil, water, animal and human tissues sampling, Two risks assessments evaluated, Pilot demonstration of save food production	2006 – 2009
<b>Support of the fresh water fish production</b>	University of the Life Sciences, Prague, Czech republic	Field survey focused on possible pesticides and heavy metals contamination Monitoring of the life conditions for the grown fish	2008 - 2010